



Case Study

Project:

ASDA Living, Barnsley

Description:

Thirty-five, square Forma metal column casings have been installed at ASDA Living's recently opened store in Barnsley, South Yorkshire.

The compact pre-formed casings are used to conceal structural columns in the new store and are fitted with resilient corner protectors to resist an accidental damage from shopping trolleys.

ASDA

